



Mounting aid OMH-RL28-C




- Protection from welding beads
- Simple and fast mounting

Weld slag cover model



Dimensions



Technical Data

General specifications

Accessories provided	glass M4 x 8 mm thumb screw
----------------------	--------------------------------

Mechanical specifications

Material	
Housing	Metal sheet (steel), black-coated
Optical face	glass


Suitable series

Series	RL28 RL29
--------	--------------

Step 1

- Push lens into the lip on the housing as shown.
- Rotate lens into position as shown.

Caution: Glass lens is fragile, handle with care

**Step 2**

- After lens has been rotated into its correct position. Secure it as shown below.

Caution: Do not over tighten, glass lens is very fragile.

